



**PORT OF  
CROMARTY  
FIRTH**

## **NOTICE TO MARINERS No 18 – 2020**

### **Caisson Storage Area Buoy out of Position and Unlit**

Charts –BA1889, BA1890

Mariners are advised that the Starboard Hand Lateral Buoy (Fl(2)G.6s) from the South West corner of Caisson Storage Area 3 is out of position and currently unlit

Initial Position- 57° 40.810' N 004° 11.880' W

Current position- 57° 40.780' N 004° 11.765' W

All mariners are advised to navigate with caution and should seek advice from Cromarty Firth Port Radio on VHF Ch11 or 01349 852308 if required

**Calum Slater  
General Manager**

20<sup>th</sup> November 2020