



**PORT OF
CROMARTY
FIRTH**

NOTICE TO MARINERS No 16 - 2020

Highland Deephaven Mooring buoys

Chart – BA 1890

Mariners are advised that four mooring buoys have been removed for maintenance located at the Technip Evanton spool base.

The position of the buoys are;

- 57°39.98'N 004°16.42'W
- 57°39.93'N 004°16.74'W
- 57°39.86'N 004°16.73'W
- 57°39.80'N 004°16.42'W

It is expected the buoys shall be out of the water until the middle of October.

All mariners are advised to navigate with caution. Should anyone wish to seek further information or advice they should contact Cromarty Firth Port Radio on VHF Ch11 or 01349 852308 if required.

Calum Slater
General Manager

2nd October 2020