

NOTICE TO MARINERS – No 23 - 2018

Special Mark (PAM) Buoy Fl. Y (5) 10s – Unlit

Chart BA 1077

Chart BA 1889

Reference: NOTICE TO MARINERS No. UoA/09/2018. (5th Sept 2018)

Mariners are advised that the Special Mark buoy (Fl. Y (5) 10s) deployed at the entrance to the Cromarty Firth at Lat 57° 41.39, Long 004° 00.350 for the purposes of passive acoustic monitoring is reported as being unlit.

Mariners are instructed to navigate in the area with caution. Further information can be requested from Cromarty Firth Port Radio on VHF CH 11 or on 01349 852308.

Graham Grant
Duty Marine Manager

Port of Cromarty Firth
Port Office, Shore Road
Invergordon, IV18 0HD

Date: 2st October 2018