

**NOTICE TO MARINERS – No. 27 -2021**


**Mussel Farm SW Buoy Temporarily Removed**

**Chart – BA 1889**

**Chart – BA1077**

Mariners are advised that the unlit Special Mark Buoy marking the South West Corner of the Mussel Farm in the Cromarty Firth has been temporarily removed.

**Buoy position Lat 57° 40.532N, Long 004°06.160W**



All mariners are advised to navigate with caution and should seek advice from Cromarty Firth Port Radio on VHF Ch11 or 01349 852308 if required

Graham Grant  
Marine Support Manager  
17<sup>th</sup> November 2021